

HARTZELL

PROPELLER LOGBOOK


PROPELLER MODEL PHC-J34F-1RF

PROPELLER S/N FP4817B


LOGBOOK # _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				Hartzell PHC-J3YF-1RF, September 7, 2006 Tach: 3477.8, SNEW: 00.0. This propeller installed on Cessna 210L 60507. Described maintenance is airworthy with respect to work performed. Signature <u><i>R. W. McBride, Jr.</i></u> R. W. McBride, Jr. AP2710158
				Hartzell PHC-J3YF-1RF, July 6, 2007, Tach: 3585.7, SNEW: 107.9. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service. Signature <u><i>R. W. McBride, Jr.</i></u> R. W. McBride, Jr. AP2710158
				Hartzell PHC-J3YF-1RF, August 7, 2008, Tach: 3680.3, SNEW: 202.5. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service. Signature <u><i>R. W. McBride, Jr.</i></u> R. W. McBride, Jr. AP2710158
				Hartzell PHC-J3YF-1RF, September 3, 2009, Tach: 1434.9, SNEW: 316.3. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service. Signature <u><i>R. W. McBride, Jr.</i></u> R. W. McBride, Jr. AP2710158


Hartzell PHC-J3YF-1RF, October 21, 2010, Tach: 3876.9, SNEW: 387.5. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service.

Signature  R. W. McBride, Jr.
AP2710158


Hartzell PHC-J3YF-1RF, November 1, 2011, Tach: 3909.2, SNEW: 425.6. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service.

Signature  R. W. McBride, Jr. AP2710158


Hartzell PHC-J3YF-1RF, February 1, 2013, Tach: 3942.6, SNEW: 459.0. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service.

Signature  R. W. McBride, Jr. AP2710158

Hartzell PHC-J3YF-1RF, June 20, 2014, Tach: 4002.2, SNEW: 518.6. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service.

Signature  R. W. McBride, Jr. AP2710158

D: Hartzell PHC-J3YF-1RF, N210HZ, July 27, 2015, Tach: 4052.9, SNEW: 569.3. Profiled blades as necessary. This propeller inspected in accordance with a 100-hour inspection and is approved for return to service.

Signature  R. W. McBride, Jr. AP2710158

Chuck's Aircraft LLC. Austin Executive Airport

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP1092A
REG. NO: 210HZ
WORK ORDER: 1734



Chuck's Aircraft, LLC.

6200 Aviation Dr. AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 9/1/2016
A/C TSN: 4060.1
PROP TT: 572
TSPOH:
TACH: 4054.3


Prop Entries

Profiled blades as necessary.

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 9/1/2016

SIGNED:



Robert McBride, Jr., IA: 2710158IA

Work Order: 1734

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP1092A
REG. NO: 210HZ
WORK ORDER: 2401



Chuck's Aircraft, LLC.

6200 Aviation Dr. AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 11/2/2017
A/C TSN: 4064.7
PROP TT: 576.3
TSPOH:
TACH: 4058.9

Prop Entries

Lubricated hub with Aeroshell #6, inspected blades, spinner and backplate.

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 11/2/2017

SIGNED:

Work Order: 2401

Robert McBride, Jr., A&P: 2710158

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP1092A
REG. NO: 210HZ
WORK ORDER: 3084



Chuck's Aircraft, LLC.

6200 Aviation Dr. AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 1/4/2019
A/C TSN: 4083.4
PROP TT: 595
TSPOH:
TACH: 4077.6

Prop Entries

Profiled blades as necessary, inspected spinner and backplate.

Technicians Who Worked On The Items Listed Above:

Robert McBride, Jr

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 1/4/2019

SIGNED:

Work Order: 3084

Robert McBride, Jr., A&P: 2710158

Printed by EBis 3 (datcomedia.com)

HARTZELL PROPELLER INC.

One Propeller Place

Piqua, Ohio 45356-2634 U.S.A.

Telephone: 937.778.4200

Telèx: 4332032

Fax: 937.778.4391