

MCCAULEY™

**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**

N5724V

PAGE NUMBER

[illegible]

PAGE NUMBER

A&P 2736512 1A

PROPELLER ASSEMBLY LOG

PAGE

REG #: N724V; MODEL: 2A37C223/90RB-6; S/N#: 160091; DATE: 3/18/2018; TSN: 82.33

Propeller Log Entry

Inspection Items Complied with:


1. Annual/100hr Inspection IAW Beech Bonanza 35 Series Shop Manual 100hr/Annual inspection guide.

AD's/Service Bulletins Accomplished:

1. AD's checked through bi-weekly 2018-05

All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the 35 series Shop Manual.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition.



Jeffrey J Hettling


A&P 2736512 IA

ure &
icate
iber

McCauley Propeller Model: 2A37C223-C. S/N: 160091. Propeller Total Time: 102.7.

Completed 100 hour inspection IAW 14 CFR Part 43 Appendix D and current Beechcraft Bonanza series maintenance manual 100 hour checklist as a guide.

Juan Morales



AP 2840494


3/31/2019

J R Aviation Services
15790 Dooley Rd. Suite 214
Addison, TX 75001

BLADE LOG

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
			Arispe Aviation LLC 1704 Canyon Wren Dr. McKinney, Tx 75071 BEECH V-35 N5724V S/N D-8103 Tach Time 2187.2 Date 20Dec19 McCauley 2A37C223/90RB-6 S/N 160091 TSN 168.2 Installed Serviced McCauley P/N 2A37C223-C S/N 160091 The aircraft identified above was maintained and altered in accordance with the current Federal Aviation Agency Regulations, Aircraft Service Manual, Radio Manufacturers Installation Manuals, and is hereby approved for return to service with respect to work performed. Anthony Arispe I.A. 3381156  Signature _____ Date 20DEC19		
			BYAM propeller svc etc work order # 40468		

PROPELLER
LOG

Byam Propeller Service, Inc.

4001 North Main St
Hanger 7S
Fort Worth, TX 76106
817-625-0161

Invoice

Date	Invoice #
12/2/2019	40668

Bill To
David Nazem 972-670-3911

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
N5724V			12/2/2019			

Quantity	Item Code	Description	Price Each	Amount
5	Labor	Service on McCauley Model Number: 2A37C223-C Serial Number: 160091	94.00	470.00
1	polane paint	polane paint	105.00	105.00
1	1633-3	1633-3 oring	4.10	4.10T
2	1633-9	1633-9 oring	3.00	6.00T
1	1633-12	1633-12 Oring	6.90	6.90T
2	1633-109	1633-109 oring	63.75	127.50T
2	1750-4	1750-4 Stat-O-Seal	10.05	20.10T
2	1633-58	1633-58 oring	2.40	4.80T
2	1633-99	1633-99 oring	5.36	10.72T
1	6480	6480 Gasket	10.85	10.85T
2	3150-5	3150-5 Roll Pin	1.40	2.80T
1	1000cc	1000cc red dye oil	37.50	37.50T
1	PLI	PLI	24.76	24.76
		Sales Tax	8.25%	19.08

Beginning Jan 1 2015 all unpaid invoices will have 5% interest added every 30 days until paid in full



Total

\$850.11

BLADE LOG

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
			Arispe Aviation LLC 1704 Canyon Wren Dr. McKinney, Tx 75071 BEECH V-35 N5724V S/N D-8103 Tach Time 2187.2 Date 20Dec19 McCauley 2A37C223/90RB-6 S/N 160091 TSN 168.2 Installed Serviced McCauley P/N 2A37C223-C S/N 160091		
			The aircraft identified above was maintained and altered in accordance with the current Federal Aviation Agency Regulations, Aircraft Service Manual, Radio Manufacturers Installation Manuals, and is hereby approved for return to service with respect to work performed.		
			Anthony Arispe I.A. 3381156		
			 		
			Signature _____ Date _____		
			BYAM propeller svc etc work order # 40468		


PROPELLER ASSEMBLY LOG

Propeller Log Entry

Reg # N5724V MFG McCauley Model 2A37C223-C Serial # 160091
 SNEW 191 Hr Meter 2210 TT 191

- " Researched AD's thru 2020-08 (summary provided)
- " R&R propeller after repair by Texas Aircraft Propeller (WO# 18677)
- " Inspected hub and spinner assy IAW SB, satisfactory
- " Dynamically balanced engine / propeller assy IAW ACES guide to dynamic bbalancing using 2020 pro-balancer, final solution = .11 IPS with 47.4 grams of weight installed
- " Reduced take off RPM to 2700 as required

I certify this propeller was inspected in accordance with a 100 hour/Annual inspection and is determined to be in airworthy condition. Returned to service this date.

Signature:  Date: 5/5/2020
 David Beaver AP 3097750 IA 8320 Thora Lane, #F-1, Spring, TX 77379, 713-851-8960

Signature &
Certificate
Number

BLADE LOG

PROPELLER

1. Approving Civil Aviation Authority / Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 18677	
4. Organization Name and Address: TEXAS AIRCRAFT PROPELLER & ACCESS 1711 CR 130 - Pearland, Texas 77581		5. Work Order/Contract/ Invoice Number: 7RDR559C 18677			
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Propeller	2A37C223-C	1	160091	REPAIRED

12. Remarks:
Disassembled, and resealed IAW McCauley manual MPC200; BOM100; SPM100
Blade Model # H-90RB-6
Blade Serial # AKA26103, AKA26102

13a. Certifies the items identified above were manufactured in conformity to:
☐ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service
☐ Other regulation specified in Block 12
Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/ Authorization No.:	14b. Authorized Signature: <i>Joseph D. Kohler</i>	14c. Approval/ Certificate No.: 7RDR559C
13d. Name (Typed or Printed):	13e. Date (m/d/y): 00/00/00	14d. Name (Typed or Printed): Joseph D. Kohler	14e. Date (dd/mm/yyyy): 27/APR/2020


Signature
Certificate
Number

Propeller Log Entry

Reg # N5724V MFG McCauley Model 2A37C223-C Serial # 160091
SNEW 234 Hr Meter 2253 TT 234

- " Researched AD's thru 2021-10 (summary provided)
- " Dressed blade leading edges as needed
- " Inspected hub and spinner assy IAW SB, satisfactory

I certify this propeller was inspected in accordance with a 100 hour/Annual inspection and is determined to be in airworthy condition. Returned to service this date.

Signature:  Date: 6/16/2021
David Beaver AP 3097750-1A 8320 Thora Lane, #F-1, Spring, TX 77379, 713-851-8960

MCCAULEY

AIRWORKS

JUNE 1, 2022

2A37C223-C

10035 JUNGMEISTER LANE

S/N 160091


MCKINNEY TX. 75071

TACH 2277.8 258.8 SNEW

818-424-1131

I certify that this propeller has been inspected in accordance with the Scope & Detail of Appendix D of Part 43 100 Hour Inspection and has been determined to be in an airworthy condition at the time of this inspection.

THOMAS M JACKSON


AP27901111A

BLADE LOG

Arispe Aviation LLC 1704 Canyon Wren Dr. McKinney, Tx 75071
BEECH V-35 N5724V S/N D-8103 Tach Time 2292.2 Date 19Jul23
Continental IO-520-BB S/N 573298 ETT 1435.2
McCauley 2A37C223/90RB-6 S/N 160091 TSN 273.2

I certify this Propeller has been inspected I.A.W. an Annual inspection using the aircraft maintenance manual and was found to be in an airworthy condition at this time

Anthony Arispe I.A. 3381156

Signature

19Jul23

Date

